

# Viking Subscriber Software 23.1.4 Maintenance Release

**Release Date:** November 16, 2023

**Title:** FSN-1123-VIKING-31

## Overview

This Field Software Notice (FSN) announces the KENWOOD Viking® Subscriber Software Version 23.1.4 Maintenance Release. This release includes an update to the Armada programming software and addresses an issue where the P25 Trunking / P25 Conventional Location Services option cannot be enabled on Viking Radios.

## Software Versions

The following table lists the Viking Software items and corresponding versions included in the 23.1.4 maintenance release.

Item	Version
Armada Client	1.40.20
Armada Server	1.40.20

## Customer Issues Addressed

The following table lists the customer-impacting issues resolved in the 23.1.4 maintenance release.

Issue	Overview
<b>Location Services Disabled</b>	This fix addresses an issue where writing from Armada 1.40.13 - 1.40.19 to Viking Radios 8.36.x, or prior, will leave the P25 Trunking / P25 Conventional Location Services option disabled.

---

*For questions regarding this Field Service Bulletin, please contact the KENWOOD Viking team at 1.800.328.3911, option 3.*

EF Johnson Technologies, Inc. | a JVCKENWOOD Company  
1440 Corporate Drive, Irving, TX 75038